

Instruction for Crystal Label

- 1: Before UV printing, make sure the printer is turned on.
 - 2: Printing film called A , remove the protective layer from A (protective layer is the layer which without adhesive), lay A on the UV printer platform(adhesive side is up), and stick the four corners with tape to prevent curling (if there is an air suction device, please open the air suction).
 - 3: Print the designed logo or any artworks (in transparent PNG format) on A. The printing sequence is white ink ~ primary color ~ varnish . Use rigid UV ink .
 - 4: Take off the printed A from the UV printer. Remove the protective layer from B (transfer film called B), and laminated B with the printed A (Adhesive side stick with adhesive side) . A3 and A4 size can be scraped gently with plastic scraper, if large format size needs to be laminated with cold laminating machine.) ****If B film you buy is only one layer , then directly laminated the B on the printed A will be ok .
 - 5: The best effect can be achieved after laminated half an hour. Do not expose the printing adhesive surface in the air, otherwise the sticking effect will be affected.
 - 6: Cut the logo or artworks from the laminated A&B, then remove A. At this time, the logo has been transferred on the B . Stick the logo or artworks on the surface of the object . Press the logo surface and make it stick tightly. Finally remove B, the whole logo is transferred on the object surface .
- Application:** Stick on glass, wood, metal, ceramics, packing boxes and other hard, oil-free and clean material surfaces.

